

CONSTRUCTION PROGRESS REPORT EUROMAX HEIGHTS APARTMENTS SOUTH C MUHOHO AVENUE



Rama Homes

— Limited —

Bringing Luxury Home

MARCH 2018

1. SUMMARY OF PROGRESS OF WORKS.

Euromax Heights

Welcome to Euromax Heights Apartments, the unique haven of tranquility. Its situated in South C Nairobi Kenya, along Muhoho Avenue right opposite The CID training school.

Construction Works is on schedule and progressing on well. The contractor is focusing on concreting of the 10th Floor level and plastering works, which is currently on the 6th Floor level.

Paint work samples have been done as per the picture awaiting approval

Welding and Fabrication works sample on the first floor is also on schedule as per the pictures below.



Bringing Luxury Home



2. PICTORIAL SUMMARY OF THE AS AT FEBRUARY WORKS.

Fig. O1. Preparation of concreting of the 10th steel fixing on going



Bringing Luxury Home



Fig. 02. 10th Floor stair steel and formwork in progress



Bringing Luxury Home



Fig. 03. Lift shaft preparation for formwork and steel fixing in progress



Bringing Luxury Home



Fig. 04. Welding and fabrications for first floor sample works on going



Bringing Luxury Home




Fig. O5. Fabrication properly protected in progress as below



Bringing Luxury Home



Fig. O6. Painting sample on the first floor as below



Bringing Luxury Home



3. CONCLUSION.

The construction works is progressing on well, and we are looking to have all the subcontractors for the works by the end of March to enable smooth progress of the project.



Bringing Luxury Home

